


# Site Area has Multiple Plumes



REF: Figure 3. Monitor Well and CPT/Hydropunch Boring Locations, Cooper Drum Company Superfund Site Remedial Design Technical Memorandum for Field Sampling Results, URS, July 2006